

Parts needed to mount the 45-ALU extrusion



Mounting bracket (A)



Extrusion (B)



LED strip (C)



Cover (D)



End Cap (E)


Tools needed for mounting:

- drill
- screwdriver


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found at www.klusdesign.eu

1. Feed the power cable. Attach the mounting bracket (A) to the surface with screws.



2. Mount the LED strip (C) in the extrusion (B), insert the cover (D) and the end cap (E).



3. Connect power to the LED strip and mount the extrusion (B) in the mounting bracket.

